

OFFICE ADDRESS:

10 Hon. Gideon Street, Off Peter Odili Rd T-Amadi, Port Harcourt.
(Operations Tel: +234 (0)807 569 4478 + 234 (0)807 569 4467); (QAQC Tel: +234 (0)807 569 4479)

E-mail: info@mojustglobal.com, qaqc@mojustglobal.com Website: www.mojustglobal.com



Certificate of Thorough Examination


This report complies with the Lifting Equipment Engineers Association's technical requirements

Date of Thorough Examination: 16/08/2022	Date of Report: 16/08/2022	Report number: MGR/TV/08-22/070
---	-----------------------------------	--

Name and Address of employer for whom the thorough examination was made: TAMROSE LIMITED. Plot 7, Okuru-Abuloma Link Road, Abuloma, Port-Harcourt, Rivers State (TMC BALD EAGLE)		Address of premises at which the examination was made: HOLIFIELD JETTY WOJI	
Description and identification of the equipment: FULL BODY HARNESS Length: 6FT ID Number: 1242526		Safe Working Load(s): 140 Kg	Date of manufacture if known: Date of last thorough examination: NOT SEEN
Make: PLUS			

Is this the first examination after installation or assembly at a new site or location?		Was the examination carried out:	
YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Within an interval of 6 months?	
		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		Within an interval of 12 months?	
YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
		In accordance with an examination scheme?	
		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
		After the occurrence of exceptional circumstances?	
		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE): NONE			
Is the above a defect which is of immediate danger to persons			YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when)			YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
Particulars of any tests carried out as part of the examination: (If none state NONE): NONE			
IS THIS EQUIPMENT SAFE TO OPERATE?			YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>

Name & Qualifications of person making this report: UFUOMA OMO-ODUDU NIGERIA FACTORY ACT/ASNT LEVEL II, LEEA: FOU SPECIFICATION: BS EN 361	Name of person authenticating this report: ONOME OGBORU NIGERIA FACTORY ACT/ASNT LEVEL II, NSL, LEEA: FOU, LEG Signature:	Latest date by which next thorough examination must be carried out: 15/12/2023 Date: 17/8/22 Sign: 
Name and address of employer of persons making and authenticating this report: MOJUST GLOBAL RESOURCES LTD.		
STATUTORY INSTRUMENTS 1998 NO.2307.FACTORIES ACT CAP F1, L.F.N, 2004. Lifting Operations and Lifting Equip. Regulation 1998.		