

OFFICE ADDRESS:

10 Hon. Gideon Street, Off Peter Odili Rd T-Amadi, Port Harcourt.

(Operations Tel: +234 (0)807 569 4478 + 234 (0)807 569 4467); (QA/QC Tel: +234 (0)807 569 4479)

E-mail: info@mojustglobal.com, qaqc@mojustglobal.com Website: www.mojustglobal.com



CERTIFICATE OF THOROUGH VISUAL EXAMINATION

Client	TAMROSE VENTURES LIMITED	CERTIFICATE	MGR/TV/10-19/045
Equipment Owner/Address	TAMROSE VENTURES LIMITED Plot 7, Okuru-Abuloma Link Road, Abuloma, Port-Harcourt, Rivers State.	INSPECTOR QUALIFICATION	NIGERIA FACTORY ACT/ASNT LEVEL II NSL LEI 1-6)
Vessel	TMC ANGEL		
Location of Inspection	TMC ANGEL		
Inspection Date	22/10/2019	Next Inspection Date	21/04/2020

S/N	DESCRIPTION OF EQUIPMENT	I.D NUMBER	LENGHT	DIA	CONDITION
1	MOORING ROPE	MR02	50m	35mm	OK

SPECIFICATION: BS 2930 RESULT: At the time of Examination, no defect likely found to affect the safe use of Lifting appliance inspected. It is OK for Use.	STATUTORY INSTRUMENTS 1998 NO. 2307 Lifting Operation and Lifting Equipment Regulation 1998.
---	--

Signature of Lead Inspector (Onome O.):



Name of Inspector: DARLINGTON DOUGLAS



OFFICE ADDRESS:

10 Hon. Gideon Street, Off Peter Odili Rd T-Amadi, Port Harcourt.
 (Operations Tel: +234 (0)807 569 4478 + 234 (0)807 569 4467); (QA/QC Tel: +234 (0)807 569 4479)
 E-mail: info@mojustglobal.com, qaqc@mojustglobal.com Website: www.mojustglobal.com




CERTIFICATE OF THOROUGH VISUAL EXAMINATION

Client	TAMROSE VENTURES LIMITED	CERTIFICATE	MGR/TV/10-19/044
Equipment Owner/Address	TAMROSE VENTURES LIMITED Plot 7, Okuru-Abuloma Link Road, Abuloma, Port-Harcourt, Rivers State.	INSPECTOR QUALIFICATION	NIGERIA FACTORY ACT/ASNT LEVEL II NSL LEI 1-6)
Vessel	TMC ANGEL		
Location of Inspection	TMC ANGEL		
Inspection Date	22/10/2019	Next Inspection Date	21/04/2020

S/N	DESCRIPTION OF EQUIPMENT	LD NUMBER	LENGHT	DIA	CONDITION
1	MOORING ROPE	MR01	25m	35mm	OK

SPECIFICATION: BS 2930 RESULT: At the time of Examination, no defect likely found to affect the safe use of Lifting appliance inspected. It is OK for Use.	STATUTORY INSTRUMENTS 1998 NO. 2307 Lifting Operation and Lifting Equipment Regulation 1998.
---	--

Signature of Lead Inspector (Onome O.):



Name of Inspector: DARLINGTON DOUGLAS



OFFICE ADDRESS:

10 Hon. Gideon Street, Off Peter Odili Rd T-Amadi, Port Harcourt.

(Operations Tel: +234 (0)807 569 4478 + 234 (0)807 569 4467); (QA/QC Tel: +234 (0)807 569 4479)

E-mail: info@mojustglobal.com, qaqc@mojustglobal.com Website: www.mojustglobal.com




CERTIFICATE OF THOROUGH VISUAL EXAMINATION

Client	TAMROSE VENTURES LIMITED	CERTIFICATE	MGR/TV/10-19/046
Equipment Owner/Address	TAMROSE VENTURES LIMITED Plot 7, Okuru-Abuloma Link Road, Abuloma, Port-Harcourt, Rivers State.	INSPECTOR QUALIFICATION	NIGERIA FACTORY ACT/ASNT LEVEL II NSL LEI 1-6)
Vessel	TMC ANGEL		
Location of Inspection	TMC ANGEL		
Inspection Date	22/10/2019	Next Inspection Date	21/04/2020

S/N	DESCRIPTION OF EQUIPMENT	LD NUMBER	LENGHT	DIA	CONDITION
1	MOORING ROPE	MR05	100m	52mm	OK

SPECIFICATION: BS 2930	STATUTORY INSTRUMENTS 1998 NO. 2307
RESULT: At the time of Examination, no defect likely found to affect the safe use of Lifting appliance inspected. It is OK for Use.	Lifting Operation and Lifting Equipment Regulation 1998.

Signature of Lead Inspector (Onome O.):



Name of Inspector: DARLINGTON DOUGLAS